



# Hospital Pharmacy HVAC Final Report

Report Approved by Alberto Amezcua  
Project Completed 07/22/22




**Unit Cleaned**



**Unit Cleaned**



**Before  
Interior Duct with Louvers/Dampers**



**After  
Interior Duct with Louvers/Dampers**



**Before  
Dampers**



**After  
Dampers**



**Before  
Interior of Unit**



**After  
Interior of Unit**





**Before**  
**Interior of unit with corrosion (Supply Side)**



**After**  
**Interior of Unit**



**Before**  
**Interior Fan Motor**




**After**  
**Interior Fan Motor**



**Before  
Filter Area**



**After  
Filter Area**




**Before  
Fan Area and Blades**




**After  
Fan Area and Blades**





**Before  
Electrical Compartment**



**After  
Electrical Compartment**




**Before  
Coil Area**



**After  
Coil Area**



**Before**  
**Reverse Motor Area – Belt in good condition**  
**(Some corrosion observed)**



**After**  
**Reverse Motor Area – Belt in good condition**



**Before**  
**Interior of access doors**



**After**  
**Interior of Access Doors**



	
<p align="center"><b>Before Interior of unit</b></p>	<p align="center"><b>After Interior of Unit</b></p>
	
<p align="center"><b>Before Recommend filter switch-out soon</b></p>	

Interior unit cleaned ducts and pharmacy registers. Sporicidin was added to disinfect unit, ducts, and registers. We recommend that a protective sealant be added to metal floor corroding areas to prolong life of unit integrity. Fan belt and other components in good working order