



6 Exhaust Fans, Stacks & Hoods Final Report

Project Performed 03/28/21
Report Approved by Alberto Amezcua



Infectious Control and Equipment Protection



Infectious Control and Equipment Protection



Infectious Control and Equipment Protection



Infectious Control and Equipment Protection



Fact Action Degreaser Added



Fact Action Degreaser Added



Vacuum Inner Casing



Pressure Washing



Rinsing Hoods after Cleaning



Rinsing Hoods after Cleaning




Rinsing Hoods after Cleaning




Rinsing Hoods after Cleaning




Before



After



Before



After



Before
Typical Findings for Inner of Fans




After



Before
Typical Findings for Stacks



After



Before



After




Before




After

Typical Findings for Exterior of Fans



Before
Typical Findings for Inner of Fans



After



Before
Typical Findings for Inner of Fans




After



Before



After



Before
Extreme Corrosion



After



Before
Typical for Stack



After



Before
Typical Findings for Inner of Fans



After



Before

Typical Findings for Inner of Fans




After



Before



After



Before
Typical Findings for Inner of Stacks

After



Before
Typical for Interior of Hoods

After



Before
Typical for Hoods



After



Before



After



Before




After



**Before
Stack**



After



Note: Extreme build-up of debris and crude on systems. Recommend service to systems a minimum of once a year. This will reduce corrosion prospects and prolong life of systems without costly potential mechanical repairs.