



# FLOUR Silo #1 & #2 Final Report

Projects Performed 05/22/22 & 05/23/22  
Report Approved by Alberto Amezcua

## Silo #2



**Silo 2**



**Before  
Interior floor**



**After**



**Before  
Interior floor**



**After**



**Before  
Interior floor**



**After**



**Before  
Ceiling and bars**



**After**



**Before  
Walls**



**After**



**Team members wearing proper PPE**



**Team members cleaning ceiling**

## Silo #1



**Silo 1**



**Lock out (Bimbo)**



**Before  
Interior floor**



**After**



**Before  
Interior floor**



**After**



**Before  
Interior walls**



**After**



**Before  
Ceiling and bars**



**After**



**Before  
Walls and bars**



**After**





**Black dots are beetles**



**Observes beetles coming out of seams, floor, and walls**

***Notes:***

***Techs did not observe any organic debris, including insects such as beetles in silo #2. However, Silo #1 had some contamination of organic debris. These seem to derive from the metal interior seams of the silo. Our recommendation is to have interior seams resealed with food grade sealant.***