










Final Report AHU S-1 – Drain Pan(s) Refurbishment

Project Performed 08/08/21
Report Approved by Alberto Amezcua



 <p>Aug 7, 2021 at 7:44:04 AM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>	 <p>Aug 8, 2021 at 1:42:02 PM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>
<p align="center">Before Drain Pan with Extreme Corrosion and Breaches</p>	<p align="center">After Drain Pan Refurbished New Metal and Metal Seal Added</p>
 <p>Aug 7, 2021 at 7:45:40 AM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>	 <p>Aug 8, 2021 at 1:43:02 PM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>
<p align="center">Before Drain Pan with Extreme Corrosion and Breaches</p>	<p align="center">After Drain Pan Refurbished New Metal and Metal Seal Added</p>
 <p>Aug 7, 2021 at 7:42:56 AM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>	 <p>Aug 8, 2021 at 12:56:20 PM 1111-1115 E California Blvd Pasadena CA 91106 United States California Institute of Technology</p>
<p align="center">Before Rear Drain Pan with Extreme Corrosion and Breaches</p>	<p align="center">After Drain Pan Refurbished New Metal and Metal Seal Added</p>



Scroll to next page for **Project in Progress and Methodology** pics..



Project in Progress and Methodology

	
<p>In progress Repairs in Progress: In-lay of New Metal</p>	<p>After Complete Metal Addition with Silicon on Edges and Screwed/Bolted Down</p>
	
<p>In progress Repairs in Progress: In-lay of New Metal</p>	<p>After Complete Metal Addition with Silicon on Edges and Bolted Down</p>



Before
Repairs in Progress: In-lay of New Metal with Silicon



After
Complete Metal Addition with Silicon on Edges and Bolted/Screwed Down



To Prolong Life of New Metal a Protective Seal was Added



Metal Protection



Metal Protection



Metal Protection



Metal Protection



Metal Protection



Metal Protection