



COIL CLEANING Final Report

Project Performed 10/08/21
Report Approved by Alberto Amezcua



Unit Cleaned



Before



After




Before



After



Before




After



Before




After



Before



After



Unit Cleaned




Before

After



Before

After





Coils cleaned for both units. However, be advised that second unit is in need of new insulation...