



# MOB A Snorkel Exhaust Final Report

## System Cleaned per NFPA Standards

### Cleaning to adhere to NFPA Standards:

*NFPA 11.6.1 “Upon inspection, if the exhaust system is found to be contaminated with deposits from grease-laden vapors, the contaminated portions of the exhaust system shall be cleaned by a properly trained, qualified, and certified company or person(s) acceptable to the authority having jurisdiction.”*

*NFPA 11.6.2 “Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to remove combustible contaminants prior to surfaces becoming heavily contaminated with grease or oily sludge.”*

Report Approved by Alberto Amezcua



**Before  
Exhaust Port on Rooftop**



**After  
Exhaust Port on Rooftop**



**Before  
Media Filter**



**After  
Media Filter**




**Before  
Exhaust Fan**



**After  
Exhaust Fan**







**Before  
Duct Work**




**After  
Duct Work**




**Before  
Area Protected**



**After  
Terminal Cleaning**



**Before  
Snorkel**



**After  
Snorkel**





**Before  
Snorkel**



**After  
Snorkel**



**Before  
Snorkel**



**After  
Snorkel**



**Before  
Snorkel**



**After  
Snorkel**



**Before  
Duct**

**After  
Duct**



**Before  
Duct**


**After  
Duct**



**Before  
Snorkel**

**After  
Snorkel**







**Before  
Duct**

**After  
Duct**



**Before  
Duct**

**After  
Duct**



**Before  
House Keeping**

