



FOOD PLANT INTERIOR Oven Final Report

Project Performed 03/20/22
Report Approved by Alberto Amezcua



Universal Stove Entry



Universal Stove Entry



Mid Access



2nd Mid Access



Interior View Points



Interior View Points



Ground Protection



Ground Protection



Team in Action, PPE Equipment in Use



Team in Interior of Oven



Debris and Some Damage to Metal Interior



Clean Interior



