



Café Restaurant Final Report


System Cleaned per NFPA Standards

Cleaning to adhere to NFPA Standards:


NFPA 11.6.1 “Upon inspection, if the exhaust system is found to be contaminated with deposits from grease-laden vapors, the contaminated portions of the exhaust system shall be cleaned by a properly trained, qualified, and certified company or person(s) acceptable to the authority having jurisdiction.”

NFPA 11.6.2 “Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to remove combustible contaminants prior to surfaces becoming heavily contaminated with grease or oily sludge.”

Report Approved by Alberto Amezcua




**Before
Exhaust Fan**



**After
Exhaust Fan**



**Before
Drop**





**After
Drop**




**Before
Fan**




**After
Fan**


	
<p align="center">Before Interior of fan</p>	<p align="center">After Interior of fan</p>
	
<p align="center">Before Vertical drop</p>	<p align="center">After Vertical drop</p>
	
<p align="center">Decal on roof top fan power panel</p>	



	
<p align="center">Before Fire prevention components</p>	<p align="center">After Fire prevention components</p>
	
<p align="center">Before Exterior of hood</p>	<p align="center">After Exterior of hood</p>
	
<p align="center">Before Access opening in duct</p>	<p align="center">After Access opening in duct</p>







Note: System in good working order and clean...